PE Number	Date reported I	ncident Start Date	Incident Start Time	Overall assessment of event	Event outcome	Final Comment T	ype of Incident	Description of Incident as reported to Environment Canterbury	No. Reports per Day COMPLETE	Activity Date CHECKED	Activity
PE185459	21/05/2018	21/05/2018	15:00	Event not Substantiated	Unable to Attend	Noted for the record	Dust	21/05/2018 03:20pm - Dust is really bad on Miners Road. Not sure of exact address. Think it is Fulton Hogan. Noticed 15 mins ago. Could barely see due to dust. Sent photo to Winston Peters and Eugenie Sage. Outside of the quarry two trucks were leaving and it was a dense fog. Would like a call back with a PE number.	1	21/05/2018	Pol Phor
PE185698	21/06/2018	20/06/2018	15:40	Event not Substantiated	Unable to Attend	Incident reported after fact. Incident report received by Fulton Hogan	Dust	21/06/18 Email received 03.40 20/06/18: Snap Send Solve Location: Conservators Rd, Mcleans Island, Christchurch 7676, New Zealand Notes: Fulton Hogan were crushing and dust was billowing into the air and drifting. Fulton Hogan are supposed to have a sprinkler system over their crusher plant	1	22/06/2018	Pol Phor
PE20140165	16/01/2014	16/01/2014	8:00	Event not Substantiated			Dust	Dust from Quarry Conservators Road. They are currently building a bund round the quarry and this is causing a lot of dust issues for callers property. he dust is very bad in a NE/NW wind. The site is large at 500 hectare.	1		
PE20151767	13/04/2015	13/04/2015	8:58	Event Substantiated			Odour	Toxic solphur smell, they said it was really bad last night, it is coming from the Quarry, maybe making coal fix for roading or something. She wants a call she has asked for this several times now	1		
PE20151811	14/04/2015	14/04/2015	13:50	Event not Substantiated			Odour	Caller phoned at 13:50 complaining about the current sulphur odour that has been noticeable at 190 Old West Coast Road for the last hour. This is the worst they've ever noticed it to be. It is a toxic sulphuric smell. The complainant is not sure where the smell is coming from, but thinks it's coming from one of the quarries on Johns Road. There is little wind there presently they said. They've talked to [ECan staff member] about this already for the previous incidents and wanted to let him know it's even worse	1		
PE182417	26/08/2017	26/08/2017	11:34	Event not Substantiated	No Environmental Impact	Not able to substantiate the complaint	Dust	26/08/17 11:41am Message: A lot of dust coming from the quarry road on Miners Road between West Coast Road and the Old West Coast Road and also out of the crusher in their yard	1	26/08/2017	Pol Phor
PE184329	7/02/2018	1/02/2018	8:00	Event not Substantiated	Unable to Attend	Customer making Ecan aware of video on internet that shows dust blowing across a road.	Dust	07/02/2018 8:00am - Email - Have you seen the video of the Fulton Hogan quarry up by the West Cost Road near Yaldhurst/Templeton doing the rounds showing Fulton Hogan failing to mitigate the dust from the quarry as required in their resource consent for the quarry? I would like to complain about this failure for them to meet such a basic condition of their consent. Hopefully the video captured 1st February 2018 is linked below showing the dust and the haze created by the quarry. https://www.facebook.com/yaldy.yaldhurst.7y/deox/122495705231847/ I would appreciate feetback as to Earn's actions in dealing with this violation on Fulton Hogan's part. Hook forward to hearing from you soon. **FOLLOW UP REQUEST** 17/02/2018 7:29PM - EMAIL: "Hello I am looking to find out how the processing of my complaint surrounding the non-mitigation of dust at a Fulton Hogan quarry is going? I was informed that I would be contacted within 2 days and that was on the 7th of February. I would greatly appreciate some form of infomation and an expected process. Regards,".	1	23/02/2018	Corres
PE184902	27/03/2018	27/03/2018	19:30	Event not Substantiated	Unable to Attend	After hours call	Dust	27/3/18 07:38pm Great clouds of dust blowing over house from Fulton Hogan Mcleans Island, dust sitting and no wind blowing it away	1	28/03/2018	Pol Phor
PE185242	1/05/2018	1/05/2018	12:15	Event not Substantiated	Unable to Attend	Fulton Hogan gave explanation that there was a spillage on Pound Road, not caused by them.	Dust	1/5/2018 1.27 p.m [Dust from Pound Road Quarry] - Caller advised there is dust coming from the Pound Road Quarry. They were there at 12.15 pm. There is no wind. There is no indication of water spraying the road to the entrance is dry and dust is being generated. complaint of dust / contaminant released into the air PE185242 Date/ Time of incident. At 12.05 pm on Tuesday 1st May. Location: Pound Road, approx 50 metres either side of the entrance to Pound Quarry. Weather conditions: Clear blue sky, well it by natural daylight/jun conditions. No wind. Extremely clear with excellent visibility in all directions. Whilst driving along Pound Road, from the direction of Templeton, luss recording on dashcam the conditions. There was no dust or visibility issues at all along either Waterloo Road, or the Templeton end of Pound Road. Visibility was clear for hundreds of metres. As I continued on this direction of travel Could see that visibility shead became reduced by what appeared to be dust in the air. As I approached I could see Clearly that this was concentrated in the area of Pound Road outside the quarry, for a distance of approx derives in each direction. I parked up close to where the dust was and took numerous photographs, whilst keeping the car running so I could continue filming and adding documentary as evidence. Once I had filmed and photographed for approximately I O minutes I continued along Pound Road outwards the roundabout with Buens Road. As I cleared the entrance to the quarry visibility again increased to the extent it was perfectly clear. When I got home I took a photograph of the area I live to show you exactly how good the visibility and weather conditions are. This supports the fact there was DEFINITELY DUST and the related contaminants in the int. And that the dust emanated from the Pound Road Quarry. I noticed as I drove by the quarry entrance there were truck tyre marks on the road surface in the form of compressed dust. There was NO indication that any truck had driven through any water spr	2	1/05/2018	Pol Phor
PE182179	4/08/2017	4/08/2017	8:00	Event not Substantiated	No Environmental Impact	Went to 333 pound rd. site is more complicated than just Fulton Hogan.	Dust	04/08/2017 11:40am - [Dust - Fulton Hogan Quarry - 333 Pound Road] - Caller who lives in Pound Road, Yaldhurst, Christchurch, reports large amounts of quarry dust on Pound Road and accumulating on their house windows. Caller stated this has been occurring for years. Caller stated the duct is coming from Fulton Hogan Quarry at 333 Pound Road and the trucks that come from this Quarry, Caller stated that they knew ECan staff monitored Old West Coast Road and requested that ECan staff also visit Pound Road.	1	4/08/2017	Pol Phor
PE185013	6/04/2018	6/04/2018	15:50	Event not Substantiated	No Environmental Impact	Made site visit but wind has dropped and no visible dust	Dust	06/04/2018 3:50pm - [Quarry dust from Pound Road & Miners Road Quarries] - Customer rang to advise of the horrendous dust that is blowing off these two quarries. Customer advises it is disgusting they can hardly breath. They would like this noted as an official complaint. **2nd Report** 06/04/2018 04:19pm - Caller reports large amounts of dust blowing off Fulton Hogan Quarry on in Pound Rd, Islington, Christchurch which is noticeable from both Pound and Buchanans Road. Noticed now (4:19pm) as Caller was driving through the area.	2	22/05/2018	,
PE20144819	20/11/2014	20/11/2014	15:21	Event Forwarded to another Agen	ncy		Dust	1521hrs - phoned from this afternoon complaining about dust from constant truck movements from the new nearby Fulton Hogan quarry. Caller used to apply oil under our PA rule as a dust suppressant, but can no longer get the oil. Apparently there is a sealed road the trucks could use, but they use this route as it's only 150 m shorter. I said I'd pass it through to you, but that we might pass it on to the DC as it's dust from the road. Caller said Fulton have been good to deal with, but they're not particularly interested in taking the other route.	1		
PE184494	16/02/2018	16/02/2018	16:45	Event not Substantiated	Unable to Locate Offender/Address	address	Odour	16/02/2018 04:49pm Caller reports large amounts of dust creating haze all along Mcleans Island Rd, Christchurch (no specific address). Caller stated that the dust is coming from all the quarries this area, including KBs quarry, Faulton Hogan quarry and Herewood quarry. Noticed just now (4:45pm). Currently a north west breeze.	1		
PE182687	25/09/2017	25/09/2017	15:00	Event not Substantiated	No Environmental Impact	CE: Made site visit but the only dust was from vehicle movements and it was not visible	Dust	25/9/2017 2.54p.m. Caller advised there was dust coming from Quarries on Conservators Road. There is a strong NW wind. Caller said the quarries include SOL, Fulton Hogan, K B Contracting, Harewood Gravel. Caller just got home now and noticed the dust.	1	24/10/2017	ħ
PE184767	16/03/2018	16/03/2018	13:00	Event not Substantiated	Unable to Attend	Not able to attend site. phoned quarry managers to make them aware of the complaint	Dust	16/03/2018 1:05pm Caller driving down Mcleans Island Rd, Christchurch reports a large amount of hazy dust in the air. Caller stated that this was coming from Sol, Issacs, Fulton Hogan, Harewood and KBs quarries. Noticed now (1pm), unknown wind direction. Caller also stated that he did not think that current dust mitigation was effective and that by the time water trucks get from one end of the road to the other the dust becomes a problem again. ** Call 2*** 16/03/18 1:40pm Caller advised their site is being covered in dust from quarry. Cars are being covered in dust. Dust gets in your eyes. They need to get a water cart going. There is southerly wind.	2	22/05/2018	r

PE182151	1/08/2017	30/07/2017	8:00	Event Substantiated	Verified but Compliant	Not from Fulton Hogan & KB Quarry. Unable to find source.	Sediment	01/08/2017 12:40pm - [Dewatering/ potential discharge to water - "XB Quarry" McLeans Island]. CCC reports an anonymous call regarding "XB Quarry" in McLeans Island (CCC did not ask for the address and did not get the caller's phone number). The anonymous caller stated that KB Quarry is pumping water out of their quarry into a nearby stock drain. The anonymous caller also stated has been occurring for the last two days and if you go to McLeans Island You can just see it". CCC had no further information on the complaint. **2NDO COMPLAINT** 03/08/2017 3-30pm - Caller advised that KB Quarry is pumping so McLeans Island Road - unsure on number - is discharging the water into the stock water race. Caller advised it happens in the evenings. Caller advised they reported a few days ago but it is still happening. Caller advised they are dewatering out of the big hole into the stock water and now the fresh clean stock water is covered in sediment. ***FOLLOW UP REQUEST FROM 2ND CALLER** 09/08/17 12:30pm - Caller rang because they would like a call back regarding PE182151.	3	9/08/2017	Þ
PE184831	21/03/2018	20/03/2018	16:57	Event not Substantiated	Unable to Attend	Not notified until next day	Dust	Email received 20/03/18 4:57pm: massive dust cloud around fulton bogan/kbs quarries residents live near these quarries, where is the dust mitigation?? this is a continual problem!!! **2nd Report** - [Dust - Miners Road/Fulton Hogan Quarry] - 21/03/2018 2:44pm - Caller reports seeing and breathing "intense amounts of dust" while driving down Miners Road [McLeans Island - Templeton] today at 11:30am near the Fulton Hogan Quarry (which is at 24 Miners Rd, Templeton.	2	21/03/2018	Pol Phor
PE163934	23/11/2015	21/11/2015	10:00	Event not Substantiated	Noted	Not investigated due to lack of resources.	Dust	Reference SR 15006351. These are a series of photographs taken Saturday morning with this truck coming off the shingle part of Kerrs Road. The driver of this truck had the courtesy to stop and was travelling at a reasonable speed on this occasion, however it shows the level of pollution raised so you can imagine how horrific this is when the trucks travel at speed (which most of them dolpoth to and from the quarry and every 1/2 hour on some days. The driver inclinated that this was the level of pollution raised so you can imagine how horrific this is when the trucks travel at speed (which most of them dolpoth to and from the quarry and every 1/2 hour on some days. The driver is the paid then this was the most economical scenario for his Company. I have to say that he took the pollution aspect for us on board and we did not see him again which has not been the usual response from Elliesmere Transport. He also indicated that he had not been given any instruction or otherwise from Road Metals Quarry regarding the use of Kerrs Road for Quarry business which is disappointing. We have had Fulton Hogan and the say read that the had not been given any instruction or otherwise from Road Metals Quarry regarding the use of Kerrs Road for Quarry business which is disappointing. We have had Fulton Hogan and the say read that the had not be not further movement from his trucks on Kerrs Road, he has also said should it happen again we are to contact him immediately. The ironic thing in all this is that the Council have to frequently repair the potholes at the You Chain road end of Kerrs road and carry out "general maintenance" on the shingle part and on the total control have to frequently repair the potholes at the You Chain road end of Kerrs road and carry out "general maintenance" on the shingle part and set is monother for the trucks? If the money is available for these kind of activities then surely the very least we could ask for is a "slow" sign to mark the shingle area or a small amount of scaling (say 2-300 mtrs) int	1		
PE183380	21/11/2017	21/11/2017	8:00	Event not Substantiated	No Environmenta Impact	l Noted for the record	Dust	21/11/17 9:40am Caller rang to report dust on West Coast Road. They said everyday there is a barrage of dust on the road. They are concerned about road safety and said there is no traffic management. I referred him to the council to talk about road safety. They said Road Metals (394 West Coast Road) and Fulton Hogan (24 Miners Road) cause dust all along the road.	1	9/01/2018	ı